95

Sectt. II-27—40,000—14-10-36.

Revenue (1938) Department.

Mis SERIES.

G.O. No. 2976

DATED 21. 11 38

[Despatch Abstract.]

Ku[illegible] - (Bellary) - Harpanahalli Taluk - Herada Village - [illegible] Tank - Repairs to the supply channel - Estimate - Sanctioned.

C.F. 31—17,006—9-2-37.

Revenue - **DEPARTMENT.**

ASSISTANT SECRETARY TO GOVT. REVENUE
6 OCT 1938

Received 19

CURRENT No. Rev 7214

Registered 6.10.38 19

XI

Subject.

Kudimaramath - (Bellary) - Harpanahalli Taluk - Hyarada village - Maliyamma tank - Repairs to supply channel - Estimate for Rs.450/- Sanction - Requested -

---

Reference-No.M-6760/38.1,

Station Madras, *Dated the* 30th September 1938.

From D.I.R.Muir, Esquire, I.C.S.,

Joint Secretary,

Board of Revenue.

T.Austin, Esquire, I.C.S., Commissioner of Land Revenue and Settlement.

:-:

Read the following paper:-

Letter from J.W.Pritchard, Esquire, I.C.S., Collector of Bellary, Ref.A-2-No.757/38 dated the 29th July 1938.

:::

The supply vanka to the Maliyamma tank at Hyarada, in Harpanahalli taluk is silted up and the bed and slopes are over grown with scrub jungle. There are boulders in the bed of the channel here and there. The scrub growth and the -- boulders have to be removed and the silt cleared. Silt clearance has to be done by the ryots but they have not attended to this work at any time before and the channel is in a very neglected condition. On account of the general economic depression the ryots are not able to do this work or contribute any portion of the expenditure. They are however willing to keep the supply channel in good repair by kudimaramath labour in - future if the channel is once repaired at the cost of Government.

Government.

I recommend that an expenditure of Rs.450/- may be sanctioned under B.S.O.No.86-5 sub-paragraph 3. The estimate prepared by the Minor Irrigation Overseer is submitted for perusal.

Belar
p 486 of
B.S.O. Vol. II
[illegible]

REFERENCE.

Submitted to the Government.

2. In view of the present condition of distress in the District, the Board requests that the Government may be pleased to sanction the estimate for Rs.450/- for repairing the supply channel to the Maliyamma tank in the Hyarada village, Harpanahalli taluk, Bellary District and to direct the execution of the work at the cost of the Government.

3. The Collector will be instructed to enforce kudimaramath regularly in future.

Ramachandran
for Joint Secretary. 6-10-38

To the Secretary to Government, Revenue Department, with the estimate.

Belar

c.n.n./4-10-1938.

[illegible] 4/10

26
7/10

Dpp Notes

3

Revenue Dept.

Memo No. 7214F/38-1 D/ 7.10.38

Kudimaramath - (Bellary) - Harpanahalli taluk - Idyarada village - Malyamma tank - Repairs to supply channel - Estimate.

From the Board of Revenue. Ref. No. M.6760/38-1 D/ 30.9.38

C/f

The Board of Revenue is requested -

(i) to report in whose charge the tank and the supply channel are, and

(ii) to indicate the source from which the expenditure on account of the repairs to the supply channel can be met

To

The Board of Revenue

Dpd M.g. 8/x

6.10.38
W 6/10

7/10

Note.

The tank and the supply channel do not find a place in the lists of M.C. sources in charge of the Rev: and the Pro. depts.

6.10.38 W 6/10

C.F. 31—14,000—7-7-37.

Revenue **DEPARTMENT.**

ASSISTANT [illegible] TO GOVT.
8-NOV 1938
REVENUE DEPARTMENT

CURRENT No. Rev 8140F
8.11.38

Received ________________19 *Registered* ________________19

Subject.

Kudimaramath - (Bellary) -Harpanahalli taluk - Hyarada village - Maliyama tank - Repairs to supply channel -Estimate.

Reference No. M. 6760/38-3

Station Madras, *Dated the* 4th November 1938.

From

D.I.R. Muir Esq., I.C.S.,
Joint Secretary,
Board of Revenue.

T.Austin Esq., I.C.S.,
Commissioner of Land Revenue and Settlement.

Read the following:-

p 3 a-b

Memorandum from Government, Revenue department No. 7214 F/38-1 dated 7th October 1938.

Reference

The tank at Hyarada village and the supply channel are in charge of the Revenue department. The expenditure on account of the repairs to the supply channel will be met from the provision under "18. Irrigation -Minor Irrigation -Revenue Department- h- Maintenance and Repairs - A.Ordinary areas.

Ramachandran
for Joint Secretary. 5.11.38

To the Secretary to Government, Revenue department.

M.S.V./4-11.38.

7

Revenue Deptt

Kudimaramath - (Bellary)
Harpanahalli taluk - Herada village
Maliyamma tank Repairs to supply
Channel

(Cm 7214 F/38)

From the Board of Revenue. Ref
No. H. 6760/38-1 dt 30.9.38.

pp 1-2 cf

~~Ex~~ Memo to do. No. 7214 F/38-1 dt 7-11-38.
(Cm. 8140 F/38) From do. Reply. No H. 6760/38-3
dt 4-XI-1938

p 3 cf
p 5 cf

To. Under Secy,

Please see the papers and the cf.

2. The list of minor irrigation sources in charge of the Rev: Deptt shows that the ~~Hy~~ Maliyamma tank in Hyarada village is in the Hadagalli taluk According to the list of villages there is no village known as Hyarada. There is a village called Herada. ~~[illegible]~~ This village was originally in the Hadagalli taluk and was transferred to the Harpanahalli taluk in G.O. No. ~~[illegible]~~ 144 Rev: dt 20.1.1932. Evidently the tank is in the Herada village and that Hyarada and Herada are one and the same village. It

Not put up

Not p 75 of List of villages. No 27
They are identical

p 11 - para 4 p 70 of [illegible]
[illegible]

does not appear necessary to ask the Board about this

3. A draft order is submitted for approval. It may be sent to Finance for acceptance.

Under Rule 9(3)(b) [illegible] (K)

Asty
14.11.38
W
14/11

HW 15/11

Fin

Rev. MD 7214 F/38-2
15/11

~~Fin (Exp)~~

The draft order may be accepted and the case returned to Rev.

DR
16.11.38

Clir
16.11.38

VG
17.11.38

MJ 17/11

Rev

VG

Fin No 41297 Exp 1
7/11/38

ASSISTANT SECRETARY TO GOVT.
18 NOV 1938

ASSISTANT SECRETARY TO GOVERNMENT
15 NOV 1938
FINANCE DEPT.

Issue HW 18/11

41297 Exp
Rev. 8390 F
18.11.38

9
21/11

9

C.F. 16.

DRAFT FOR APPROVAL.

Revenue Dept.

	Date.	Initials.
When received for fair copying	21/11	
When copied		
When examined		
When signed		
When despatched.		

SUBJECT :—

READ AGAIN ________, dated ________ 19__.

" " ________ " ________ 19__.

READ ALSO :—

No. 7214 F/38 From the Board of Revenue No. Ref. M. 6760/38-1, dated 30.9.1938 1 1
" ________ " Memo to do. 7214 A/38-1 " 7-10-1938 p. 3-4
" 8140 F/38 " from the do. Ref. M. 6760/38-3 " 4-11-1938 pp 5-6

~~Resolution~~ Order ~~Rent.~~ Ms. No. 2976, dated 21. 11. 1938.

(2)

Spl. Substitute slip

p 2-7

The Government sanction, as a special case and for this occasion only, the execution at a cost not exceeding Rs 450 (Rupees four hundred and fifty only) of repairs to the supply channel to the Maliyamma tank in the Herada village of the Harpanahalli taluk, Bellary district, subject to the condition that the ryots should keep the supply channel in good repair by kudimaramath in future.

10

2 The expenditure should be met from the ~~[illegible]~~ provision ~~[illegible]~~ under '8 Irrigation - Other Rev: Expenditure financed from Ordinary revenues - Minor Irrign - Revenue Dept. - L. Maintenance and repairs - A Ordinary areas".

14.11.38

14/11

15/11

To

The Board of Revenue.
(with estimate returned)
Thro'
Finance dept.
A.G. Rev. Fin.

Dpd. by Van / Post / Messenger
Dpr.'s initials
Date 21-XI 1938.